INDIAN INSTITUTE OF TECHNOLOGY, MADRAS ELECTRICAL DIVISION ENGINEERING UNIT

Date: 19/12/2012

CORRIGENDUM

T.NO: 34/2012-13/ELDB

- 1. The losses for the 1000kVA 11/0.433kV Distribution Transformer shall be as per IS.
- 2. In item No.4 for the length of the CI pipe read 3 mtrs instead of 300 mm.

-Sd-Consultant (Elect) -Sd-Executive Engineer (E)